

<https://pchub.com/server-power-supply-250w-prn250m-p156033>

PRT PRN250M Server - Power Supply 250W, PRN250M

Item Condition	Used
Warranty	1 Month(s)
Model / GTIN	-
Part Description	-
Part Number	-
Info 3	-
Info 4	-

MODEL: PRT250H
SWITCHING POWER SUPPLY



1757000028

PRT MODEL: PRT250H
SWITCHING POWER SUPPLY

U (V)	100-240Vac	0.85A	50 Hz	0.75C	
Output	+5	+12	+15	-12	+5
25W	25W	25W	15W	15W	25W
Reg.	-0.1	0.05	-0.3	0.05	0.1

WARNING
 Attention: Switching power supply. Do not touch the output terminals when the power is on. Read the manual before use.

ATTENTION
 Attention: Alimentation à découpage. Ne touchez pas les bornes de sortie quand l'alimentation est sous tension. Lire le manuel avant utilisation.

WARNING
 ATTENTION: Switching power supply. Do not touch the output terminals when the power is on. Read the manual before use.

PELIGRO
 Atención: Alimentación a decoupage. No toque las bornas de salida cuando la alimentación está encendida. Leer el manual antes de utilizarlo.

LEVEL 1 C 04/11/05
 MADE IN CHINA 28 0164867



MODEL: PRT250H
SWITCHING POWER SUPPLY



1757000028

PRT MODEL: PRT250H
SWITCHING POWER SUPPLY

U (V)	100-240Vac	0.85A	50 Hz	0.75C	
Output	+5	+12	+15	-12	+5
25W	25W	25W	15W	15W	25W
Reg.	-0.1	0.05	-0.3	0.05	0.1

WARNING
 Attention: Switching power supply. Do not touch the output terminals when the power is on. Read the manual before use.

ATTENTION
 Attention: Alimentation à découpage. Ne touchez pas les bornes de sortie quand l'alimentation est sous tension. Lire le manuel avant utilisation.

WARNING
 ATTENTION: Switching power supply. Do not touch the output terminals when the power is on. Read the manual before use.

PELIGRO
 Atención: Alimentación a decoupage. No toque las bornas de salida cuando la alimentación está encendida. Leer el manual antes de utilizarlo.

LEVEL 1 C 04/11/05
 MADE IN CHINA 28 0164867

